



Damaged stretchers are common in the Pre-Hospital environment, and have been shown to harbour dangerous pathogens that contribute to Healthcare-Associated Infections. An April 2013 US FDA Safety Communication warned of the risk of blood and bodily fluids entering into mattresses, leading to risk of Patient infection. "Taping the damage" is unsafe and prohibited by surveyors.



CleanPatch® is a CE mark, first-in-class medical surface repair product that restores damaged stretcher mattresses to an intact and hygienic state. Applied in seconds, CleanPatch is already being used by more than 450 Healthcare facilities and Emergency services to comply with safety standards, save money AND enhance Patient safety!

CleanPatch has been proven to be:



DURABLE IN HEALTHCARE



CLEANABLE BY DISINFECTANTS



IMPERVIOUS TO FLUIDS



EQUIVALENT TO THE SURFACE



Use CleanPatch® as part of a Mattress Inspection and Repair program in your facility, to cost-effectively repair your stretcher mattresses!

Three Sizes available for purchase today;

- 2 inch (5 cm) circle
- 3.5 inch (9 cm) square
- 3.5 x 6 inch (9 x 15cm) rectangle



FERNO®

Contact Ferno for more information and to order CleanPatch®

Ferno (UK) Ltd, Ferno House, Stubs Beck Lane, Cleckheaton, BD19 4TX
Tel: 01274 851999 Email: sales@ferno.co.uk Web: www.ferno.co.uk